

BCA Guidance Notes



| No. | Title | Issue | Date | Status |
|-----|--|-------|-----------|----------------|
| 1 | Glass guarding and restrictors to low level windows above ground floor level in dwellings | 1 | Sept 2016 | Current |
| 2 | Protected Entrance Halls | 0 | Jan 2011 | Current |
| 3 | Guide to Vertical Circulation in Non-Domestic Buildings | | | Under Revision |
| 4 | Application of B1 to Loft Conversions Works and Fire Doors to Protected Stairs | 1 | Jan 2012 | Current |
| 5 | Notification requirements for Controlled Services and Fittings | 0 | Jan 2011 | Current |
| 6 | Use of multi-foil insulation products and compliance with Regulation 7 and Requirement L1 | 2 | Jan 2013 | Current |
| 7 | Resistance to the Passage of Sound—Acoustic Testing Requirements | 0 | Jan 2011 | Current |
| 8 | Smoke Shaft Termination at Roof Level | 0 | Jan 2011 | Current |
| 9 | Fire Doors in Dwellings | 1 | Jan 2013 | Current |
| 10 | Installation of boiler flues and ventilation perforations in external timber framed walls and other such structures. | 0 | Jul 2011 | Current |
| 11 | Interim Guidance on the transfer of sewers to water companies under The Flood and Water Management Act | 0 | Nov 2011 | Current |
| 12 | Cavity Separating Wall Guidance for Part L 2010 | 0 | Dec 2011 | Current |

| | | | | |
|----|--|-----|-----------------------|---------|
| 13 | Not allocated | n/a | n/a | n/a |
| 14 | Guidance on Robust Details Notifications to Building Control Bodies | 2 | Sept 2016 | Current |
| 15 | Sizing of Package Sewage Treatment Plants | 0 | Jan 2013 | Current |
| 16 | Guarding to windows opening with low cill heights | 1 | Sept 2016 | Current |
| 17 | Evidence of Mechanical Flow Rate Testing—Testing of Fixed Fans | 0 | Oct 2013 | Current |
| 18 | Use of Combustible cladding materials on tall buildings | 1 | Jun 2015 ¹ | Current |
| 19 | Use of Timber Stairs in Residential Buildings Exceeding Three Storeys | 0 | Jun 2014 | Current |
| 20 | Ensuring adequate ventilation to naturally-ventilated dwellings with high levels of as-built air tightness | 1 | Mar 2015 | Current |
| 21 | Disproportionate Collapse | 0 | Dec 2014 | Current |
| 22 | Assessment of proposed robustness measures following the 'Alternative approach' given in Approved Document A Section 5 paragraph 5.4 | 0 | Dec 2014 | Current |
| 23 | Means of Escape from Enclosed Private Balconies to Flats | 0 | Dec 2014 | Current |
| 24 | Means of Escape from Dwelling Houses with Four or More Storeys | 0 | Dec 2014 | Current |
| 25 | Guarding to Balconies | 0 | Sept 2016 | Current |
| 26 | Service Penetrations through External Wall Constructions of Residential Buildings | 0 | Apr 2017 | |

¹ From October 2018, this Guidance Note will need to be read in association with its cover page and Government Circular Letter.